


XL-Rugged-117 1000A 500ERPM run2

Input Voltage & Phase Current



Temperatures

