


XL-Rugged-88 1000A 500ERPM run1

Input Voltage & Phase Current



Temperatures

